

## Cherry BX-2 Supplement # 4

Horizontal stabilizer bearing: Worn out bearings can be replaced (according to the sketch "neu" = new) by simple Nylon (PA)-bearings (D 040/1)

